


4.1. BARLINDALEN GRUVER

M=1:250


Gj. L=22.-m



Snitt A-B


Dårlig gj.

Gjerde L=32.-m.




Snitt A-B

Dårlig gj. L=27.-m




Snitt A-B

Inntakt gj. L=27.-m




Snitt A-B

Defekt gj. L=36.-m




Snitt A-B

Gj. inntakt. på stengj. L=32.-m.




Snitt A-B


Dårlig gj. Vannfylt. Gj. L=38.-m



Dårlig gj. L=28.-m. Vannfylt




Gj. inntakt L=73.-m.




Snitt A-B

Gj. inntakt oppå stengj L=45.-m



Gj. L=46.-m



Kongsberg den 7/2-1978
R. Kongsberg