

X=2000
Y=2000
Z=-100

X=2000
Y=3400
Z=-100

X=1800

X=1800

X=1600

X=1600

X=1400


X=1400

X=1200

X=1200

X=1000
Y=2000
Z=-100

X=1000
Y=3400
Z=-100



Y=2200

Y=2400

Y=2600

Y=2800

Y=3000

Y=3200

Front: 25.00

Back: 25.00

31.10.2003

1: 2000