


Fordeling av kobber i råmalmen

- Cu% ≥ 3
- 3 > Cu% ≥ 2.5
- 2.5 > Cu% ≥ 2
- 2 > Cu% ≥ 1.5
- 1.5 > Cu% ≥ 1
- Cu% < 1



MALMBEREGNING 01 01 84
 RÅMALM, TEKNISK BRYTBAR
 26.6 1984 RJ.