


M = 1:2000

Nord-linje



S.10.5



Os.


Os.
Os.

Røskvæn

Røsk

Os.

Os.



S.3.j



Os.

S.4.j
Os.

Dynamitlager

Vei til Jendal

Lagerboljebad

Stillebakkapressor

Parakker

Vedskur

Jendal-Gårdene

Røsk 5.

Røsk 4.

Røsk

Røsk 3.

S.5.j
Os.
Os.
Os.


Os.

Os.

Os. (gammel)

Røsk


Os.



Røsk 2.

Røsk 1.

S.6.j
X1
X2



S.5.j
S.1.j

Skisse

over

Søndre Hamnefelt

Optatt

med kompass & målebånd
etter anvisning av Herr. & Hamne

Kvinesdal, okt. 1941.

G. Sverdrup