



HELGEVANNSGRUVENE

M=1:250




NR. 5 GR.


Gj. L = 119,5 m Gj. inntakt



Særlig stygg dagåpning
Berghallen har traktform og går
direkte ned i dagåpningen.





Gj. L = 10,5 m
Gj. inntakt



Snitt A-B

NR. 1 GR.



Gj. L = 44,7 m



Snitt A-B

KRISTIAN VII GR.

Gj. L = 83,5 m





Gj. inntakt L = 6-m

5a

NR. 3 GR.


Gj. L = 6 m

5



NORDRE GANG


Gj. defekt i N.V. hj
Gj. L = 30 m



NR. 8 GR.

Gj. L = 40-m

Gj. defekt i S. siden av
Vinnfall



Kongsberg, den 21/12-77.
R. Høngsæd