RAIPAS MINE 20fm level

Explane
Slicks 178/15

Drive on strike of mudstone following dol. band in it

Dol. band on HW of marked pl.

Ex. plane all along drive clay in places.

Drive in pink and orange dol. Rough wall prominent along SE Intersected by flat plants at low angle across somewhat disturbed bedding

Rough wall along drive

Rubble

Dolomite

Solid dol

Pillar

Stope cut off at marked pl. 2m horiz. width 5m above level.

Stope cut for some meters above level, ends abruptly under marked pl. 340° at 25°

Blocks brown stained dol & grey clay collapsed into drive from shatter zone extending 3-4m above level.

Solid pink dol. Some qtz veins

Crush on HW. slabby

Pillar with crush zone 6 min.

Mark. Fw to stope 5m incl. hr. stoped. ≤ 150 wide.

Mudstone

Dol. band

Mudstone

Mudstone

Fw. fissure crush.

Dolom

Dol.

Crush.

Exc. 3-4 above level nadir ore zone

Cross fractures crush.

Dol.

Rust. cr. zone

Fissure crush.

Dol.

Bed. in banded mudst. reddish in parts

Sed. cont.

Rust. jt.

Dol.

Mudst

Zone of cr & sh. mudstone with br. v. qtz & pink calc.

Crush & breccia

Bed rust fissure open in parts

Sed. cont dolomite

Mark. slip plane

Wh. xst dol

Slip

Mudstone

Crush & breccia

Stope ore along breccia higher at cont. side.

Heading

Fissured zone.

Dol. sh

Sh

Dolomite

Solid dol

jt.

Slip pl. Jnts blk. crushed mudst and dol. on FW

Fault

Crushed & breccia mudst

Slicks 225/35

b.pl. Wh xst dol above pink spsd below

Bed.

Red - pink F grd dol

Pl. inters. bedding

jt

Bed steepens down dip

Opp bed. dip variable

Irreg. marked wall.

Bed. irreg.

m.pl. Fine slicks

Fold. in dol

Pl. w. clay gouge

Dol. rust. mal. stains

Slicks 305/25

Smooth wall & slope.

Sh. rust, mal

Wh. xst dol.

Bed

Wh. Fiss lim, cal. mal

Sl. pl.

Jt

Bed

Wh. xst dol

Slip

Mudstone

Sed. cont

Dol.

Dol.

Rust. fissure

Rust. Jt.

Dol.

Mudst

Crush & breccia

Bed

Rust. fissure

Dol.

Clay jt.

Jt

Dol.

Dol.

Dol.